



An ISO 9001 Certified Company

10600 N. Industrial Drive
Mequon, WI 53092-4473
262-238-1700 (Tel.)
262-238-1701 (Fax)
www.coppsindustries.com

ARMORGARD 541FST

FAST CURING, THIXOTROPIC FOAM MOLD COATING

SOLVENT FREE-ZERO VOC
SURFACE SINGLE COAT APPLICATION
LOW HEAT ON CURE

EXTREMELY TOUGH, NON BRITTLE
SEALS HOTWIRE CUT FOAM PATTERNS
DOES NOT DISTORT MOLD SHAPE

PRODUCT GENERAL INFORMATION

Armorgard 541FST is a 100 % solids, thixotropic, primerless, odorless epoxy coating for vertical surfaces of foam patterns and molds used in precast concrete applications.

Armorgard 541FST provides a convenient work life and a rapid tack free time. Armorgard 541FST was designed from conception to be the ideal foam coating.

Armorgard 541FST can be easily applied with a roller or brush. Normal application thickness is 15-30 mil (0.38-0.76 mm).

HANDLING PROPERTIES @ 77 °F (25 °C)

Table with 3 columns: COMPONENTS, Resin, Hardener, and ASTM reference. Rows include WEIGHT PER GALLON, DENSITY, MIX RATIO, COLOR, MIXED VISCOSITY, WORKING TIME, GEL TIME, TACK-FREE TIME, INITIAL CURE, APPLICATION TEMPERATURE, COVERAGE, HARDNESS, and MAXIMUM SERVICE TEMPERATURE.

\*Varies with porosity of surface

## **SURFACE PREPARATION**

To achieve excellent adhesion, the substrate should be free of all loose and foreign material and should be clean. If present, any oils, greases, or other contaminants must be removed prior to coating. Armorgard 541FST will not bond to a contaminated surface.

## **AMBIENT CONDITIONS**

Relative humidity and dew point must be determined before application to avoid adhesion failures. The dew point is used to predict the substrate temperature at which air begins to condense, in the form of water, on the substrate. Never apply a coating unless the form surface temperature is 5 °F (2.5 °C) above the dew point. This temperature difference must be observed until the epoxy coating is cured to a tack-free state. A dew point calculation chart is available from a Copps Technical Representative.

Armorgard 541FST will soften when exposed to extreme precast temperatures. A service temperature of no greater than 110 °F (43 °C) is recommended when removing forms coated with Armorgard 541FST.

## **MIXING**

Mix 5 parts A (resin) to 1 part B (hardener) for 2 minutes using a Jiffy Mixer and a slow speed drill. Mix at slow speed (less than 850 rpm) to avoid air entrainment. DO NOT mix more material than can be used within the stated working time. REMEMBER - you will have less working time at higher temperatures.

## **APPLICATION**

Armorgard 541FST can be applied with a squeegee, brush, non-shedding roller or a grooved fiberglass roller. Re-coating a used foam piece may require a light sanding to remove any residue from previous casts.

## **CLEAN-UP**

Armorgard 541FST, before it is fully cured (hard), may be removed from tools with Copps Enviro Kleen solvent or warm soapy water.

## **SAFETY PRECAUTIONS**

Avoid breathing of vapors. Forced local exhaust is recommended to effectively minimize exposure. NIOSH approved, organic vapor respirators and forced exhaust are recommended in confined areas, or when conditions (such as heated polymer, sanding) may cause high vapor concentrations. Do not weld on, burn or torch Armorgard 541FST or any epoxy material. Hazardous vapor is released when an epoxy is burned.

Avoid skin or eye contact. Wash skin with soap and water if contact occurs. If eye contact occurs flush with water for 15 minutes and obtain medical attention.

Read and understand all cautions on can labels and material safety data sheets before using this material.

## **WARRANTY AND DISCLAIMER**

Copps Industries, Inc. gives no warranty, express or implied, and all products are sold upon condition that purchasers will make their own tests to determine the quality and suitability of the product. Copps Industries, Inc. shall be in no way responsible for the proper use and service of the product. The information given in this publication is considered to be accurate and reliable and is provided as a service only. Physical properties shown are typical. Actual properties are dependent on curing conditions and degree of cure. Any information or suggestions given are without warranty of any kind and purchasers are solely responsible for any loss arising from the use of such information or suggestions. No information or suggestions given by us shall be deemed to be a recommendation to use any product in conflict with any existing patent rights.